

Elsie-Vinemaple RFPD #11

Clat_fir03A

Elsie-Vinemaple RFPD

Building Type		County	
Fire - RFPD		Clatsop	
Street			
81287 Bear Rd			
City	State	Zip	
Seaside	OR	97138	
Latitude		Longitude	
45.85607		123.54492	
Tracking Code		Inspection Date	
RVS in 2006		9/19/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	-0.5	0	0	-0.4	0	0	0.9
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Elsie-Vinemaple RFPD #11

Final RVS Score

Final Type

Final Score

RM1

0.9

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	2	No	No

Plan Irregularities	Vertical Irregularities
Torsion: Eccentric Stiffness	Soft Story
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



SW Primary Structural Type



SW Elevation View

Elsie-Vinemaple RFPD #11

Clat_fir03B

Elsie-Vinemaple RFPD

Building Type		County	
Fire - RFPD		Clatsop	
Street			
81287 Bear rd			
City	State	Zip	
Seaside	OR	97138	
Latitude		Longitude	
45.85608		123.54514	
Tracking Code		Inspection Date	
RVS in 2006		9/19/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	S3	3.2	0	0	0	0	-0.4	0	0	2.8
Secondary	W2	3.8	0	0	0	2.4	-0.4	0	0	5.8
Tertiary		0	0	0	0	0	0	0	0	0

Elsie-Vinemaple RFPD #11

Final RVS Score

Final Type

Final Score

S3

2.8

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1980
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No

Plan Irregularities	Vertical Irregularities
None	None
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



NW Elevation View

