

# Columbia Memorial Hospital - Astoria

Lutheran Affiliated NFP

Clat\_hos01A

Building Type Hospital	County Clatsop	
Street 2111 Exchange St		
City Astoria	State OR	Zip 97103
Latitude 46.18794	Longitude 123.81836	
Tracking Code RVS in 2006	Inspection Date 9/12/2006	



Seismicity Zone: Very High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	0	0	0	0	0	1.3
Secondary	URM	1.8	-1	-0.5	0	0	0	0	0	0.3
Tertiary		0	0	0	0	0	0	0	0	0

Columbia Memorial Hospital -  
Astoria

Final RVS Score

Final Type	Final Score
URM	0.3

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Columbia Memorial Hospital - Astoria

Clat\_hos01A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
	1977	1977	1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	2	No	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: Single Change (Adjacent Building/Entity)	
Reentrant Corners: Other (Adjacent Build/Entity)		Steps in Elevation View: Single Change	
None		None	
Falling Hazards		Poor Conditions	
Other: General		Open cracks in structural members	
Other: Brick Veneer		None	
None		None	
			
W	Falling Hazard	S	Poor Condition
			
S	Poor Condition	S	Poor Condition
			
E	Falling Hazard	N	Falling Hazard
			
W	Elevation View	W	Elevation View
			
NW	Poor Condition	NE	Elevation View
			
N	Elevation View	N	Elevation View



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Columbia Memorial Hospital - Astoria

Clat\_hos01A



SE Elevation View



NE Primary Structural Type



SW Elevation View



SE Other  
new bldg out patient only



S Vertical Irregularity Primary