

Astoria Police Dept

City of Astoria

Clat_pol01A

Building Type Fire - City	County Clatsop	
Street 555 30Th Street		
City Astoria	State OR	Zip 97103
Latitude 46.1909	Longitude 123.81157	
Tracking Code RVS in 2006	Inspection Date 9/12/2006	



Seismicity Zone: Very High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	-0.5	0	0	-0.4	0	0	0.9
Secondary	W2	3.8	-2	-0.5	0	0	-0.4	0	0	0.9
Tertiary		0	0	0	0	0	0	0	0	0

Astoria Police Dept

Final RVS Score

Final Type	Final Score
RM1	0.9

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Astoria Police Dept

Clat_pol01A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
	1977	1977	1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No
Plan Irregularities		Vertical Irregularities	
Lateral-Force-Resistance in One Direction Only		Steps in Elevation View: Single Change	
Torsion: Eccentric Stiffness		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	



S Building Name



NE Primary Structural Type



N Plan Irregularity Primary



NW Tertiary Structural Type
c2 columns on fire side doors



NW Elevation View



NW Plan Irregularity Secondary
wood wall on one side



NW Secondary Structural Type



W Elevation View



S Elevation View



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Astoria Police Dept

Clat_pol01A



SW Elevation View

NW Elevation View

W Other