

Seaside Police Department

City of Seaside

Clat_pol06A

Building Type	County	
EOC-Public Safety Answering P	Clatsop	
Street		
1091 S Holladay		
City	State	Zip
Seaside	OR	97138
Latitude	Longitude	
45.98705	123.92311	
Tracking Code	Inspection Date	
New Building	9/14/2006	



Seismicity Zone: Very High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	0	2.4	0	0	0	3.7
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Seaside Police Department

Final RVS Score

Final Type	Final Score
W2	3.7

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Seaside Police Department

Clat_pol06A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		1999	1990
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	2	No	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: L Shaped		Steps in Elevation View: 2 to 3 Changes	
None		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
S	Elevation View	SE	Elevation View
			
S	Vertical Irregularity Primary	S	Vertical Irregularity Primary
			
NE	Elevation View	NW	Plan Irregularity Primary
			
W	Vertical Irregularity Primary	W	Vertical Irregularity Primary
			
W	Building Name	W	Building Name



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries