


Warrenton Grade School

Warrenton-Hammond SD 30

Clat_sch08A

Building Type	County	
School	Clatsop	
Street		
820 Sw Cedar St		
City	State	Zip
Warrenton	OR	97146
Latitude	Longitude	
46.15825	123.93154	
Tracking Code	Inspection Date	
RVS in 2006	9/11/2006	



Seismicity Zone: Very High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	0	2.4	0	-0.8	0	2.9
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Warrenton Grade School

Final RVS Score

Final Type	Final Score
W2	2.9

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Warrenton Grade School

Clat_sch08A

Enrollment 546	Year Built (Field Verified) 1980	Year Built (Alt. Source) 1980	Est. Decade Built 1980
Total Area (square ft) 85000	Number of Stories 2	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners: Other None None		Vertical Irregularities Steps in Elevation View: Very Irregular Changes Building On Hill or Sloped Site None	
Falling Hazards None None None		Poor Conditions None None None	
			
SW Elevation View	NW Elevation View	N Elevation View	
			
NW Elevation View	SW Elevation View	SW Elevation View	
			
E Elevation View	E Number of Stories	NE Primary Structural Type	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Warrenton Grade School

Clat_sch08A



NE Vertical Irregularity Primary



N Other covered play area



NW Elevation View



NW General Site



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries