

Col R F&R Fire Station - Admin

Colu_fir01A

Columbia River Fire & Rescue

Building Type		County	
Fire - RFPD		Columbia	
Street			
270 Columbia Blvd			
City	State	Zip	
St Helens	OR	97051	
Latitude		Longitude	
45.86511		122.80149	
Tracking Code		Inspection Date	
RVS in 2006		9/21/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	0	0	0	0	-0.4	0	0	2.4
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Col R F&R Fire Station - Admin

Final RVS Score

Final Type

Final Score

RM1

2.4

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Col R F&R Fire Station - Admin

Colu_fir01A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1950
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No

Plan Irregularities	Vertical Irregularities
Torsion: Eccentric Stiffness	None
None	None
None	None

Falling Hazards	Poor Conditions
Parapets: General	None
None	None
None	None



W Primary Structural Type



NE Falling Hazard