

Col R F&R Fire Station - Deer Island

Columbia River Fire & Rescue

Colu_fir03A

Building Type	County	
Fire - RFPD	Columbia	
Street		
33710 Canaan Rd		
City	State	Zip
Deer Island	OR	97054
Latitude	Longitude	
45.93631	122.87269	
Tracking Code	Inspection Date	
RVS in 2006	9/20/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	-0.5	0	0	0	-0.6	0	0.7
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Col R F&R Fire Station - Deer Island

Final RVS Score

Final Type	Final Score
RM1	0.7

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Col R F&R Fire Station - Deer Island

Colu_fir03A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
	1975	1975	1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: 2 to 3 Changes	
None		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
NW Elevation View		SW Vertical Irregularity Primary	
		NE Vertical Irregularity Primary	
			
N Plan Irregularity Primary		N Primary Structural Type	