

Col R F&R Fire Station - Columbia City

Columbia River Fire & Rescue

Colu_fir04A

Building Type Fire - RFPD	County Columbia	
Street 415 G St		
City Columbia City	State OR	Zip 97018
Latitude 45.89137	Longitude 122.81239	
Tracking Code RVS in 2006	Inspection Date 9/21/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W1	4.4	0	-0.5	0	0	0	0	0	3.9
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Col R F&R Fire Station - Columbia City

Final RVS Score

Final Type	Final Score
W1	3.9

FEMA-154 Collapse Potential


Low (<1%)



OregonGeology

Col R F&R Fire Station - Columbia City

Colu_fir04A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: L Shaped		None	
None		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
E	Building Name	SW	Elevation View
			
		S	Elevation View



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Col R F&R Fire Station - Columbia City

Columbia River Fire & Rescue

Colu_fir04B

Building Type Fire - RFPD	County Columbia	
Street 400 G st		
City Columbia City	State OR	Zip 97018
Latitude 45.89249	Longitude 122.81292	
Tracking Code RVS in 2006	Inspection Date 9/21/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	0	-0.5	0	0	-0.4	0	0	2.9
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Col R F&R Fire Station - Columbia City

Final RVS Score

Final Type	Final Score
W2	2.9

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Col R F&R Fire Station - Columbia City

Colu_fir04B

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No
Plan Irregularities		Vertical Irregularities	
Torsion: Building Shape		None	
None		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
SW Elevation View			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries