

# Col R F&R Fire Station - St Helens

Columbia River Fire & Rescue

Colu\_fir06A

Building Type	County
Fire - RFPD	Columbia
Street	
105 S 12th St	
City	State Zip
St Helens	OR 97051
Latitude	Longitude
45.86133	122.81029
Tracking Code	Inspection Date
RVS in 2006	9/21/2006



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	-0.5	0	0	0	-0.6	0	0.7
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Col R F&R Fire Station - St Helens

## Final RVS Score

Final Type	Final Score
RM1	0.7

## FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Col R F&R Fire Station - St Helens

Colu\_fir06A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
	1983	1983	1980
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	2	No	Yes
Plan Irregularities		Vertical Irregularities	
Reentrant Corners:Other (Adjacent Build/Entity)		Steps in Elevation View: 2 to 3 Changes	
None		None	
None		None	
Falling Hazards		Poor Conditions	
Parapets: General		None	
None		None	
None		None	



W Plan Irregularity Primary



W Falling Hazard



N Field Verified Year Built  
1983



NE Vertical Irregularity Primary



SE Plan Irregularity Primary



SW Elevation View



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries