

Col R F&R Fire Station - Rainier

Columbia River Fire & Rescue

Colu_fir07A

Building Type Fire - RFPD	County Columbia	
Street 211 W 2nd St		
City Rainier	State OR	Zip 97048
Latitude 46.08875	Longitude 122.93714	
Tracking Code New Building	Inspection Date 9/20/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	S3	3.2	0	0	0	0	0	-0.6	0	2.6
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Col R F&R Fire Station - Rainier

Final RVS Score

Final Type	Final Score
S3	2.6

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Col R F&R Fire Station - Rainier

Colu_fir07A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
	1999	1999	1990
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	2	No	No
Plan Irregularities		Vertical Irregularities	
None		Building On Hill or Sloped Site	
None		Internal Discontinuous Diaphragm (large internal opening)	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
NW Primary Structural Type		SW Vertical Irregularity Primary	
		NE Elevation View	
			
W Building Name			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries