

# Col R F&R Fire Station - Goble

Columbia River Fire & Rescue

Colu\_fir14A

Building Type	County	
Fire - RFPD	Columbia	
Street		
69321 Nicolai Rd		
City	State	Zip
Goble	OR	97048
Latitude	Longitude	
46.00096	122.90826	
Tracking Code	Inspection Date	
RVS in 2006	9/20/2006	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	S3	3.2	0	0	0	0	0	-0.6	0	2.6
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Col R F&R Fire Station - Goble

## Final RVS Score

Final Type	Final Score
S3	2.6

## FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Col R F&R Fire Station - Goble

Colu\_fir14A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1980
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	2	No	No
Plan Irregularities		Vertical Irregularities	
None		Internal Discontinuous Diaphram (large internal opening)	
None		None	
None		None	
Falling Hazards		Poor Conditions	
Other: General		None	
None		None	
None		None	
			
SE	General Site	SW	Elevation View
			
N	Elevation View	N	Elevation View
			
SE	Falling Hazard		



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries