

Col R F&R Fire Station - Fernhill

Columbia River Fire & Rescue

Colu_fir15A

Building Type Fire - RFPD	County Columbia	
Street 73153 Doan Rd		
City Rainier	State OR	Zip 97048
Latitude 46.05743	Longitude 122.99545	
Tracking Code RVS in 2006	Inspection Date 9/20/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	S3	3.2	0	0	0	0	-0.4	0	0	2.8
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Col R F&R Fire Station - Fernhill

Final RVS Score

Final Type	Final Score
S3	2.8

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Col R F&R Fire Station - Fernhill

Colu_fir15A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1980
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	2	No	No
Plan Irregularities		Vertical Irregularities	
None		Internal Discontinuous Diaphram (large internal opening)	
None		None	
None		None	
Falling Hazards		Poor Conditions	
Other: General		None	
None		None	
None		None	



SE Elevation View



N Falling Hazard



NE Primary Structural Type



W Elevation View



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries