

Rainier City Police Dept City Hall

Colu_pol04A

City of Rainier

Building Type Police - City	County Columbia	
Street 106 W B St		
City Rainier	State OR	Zip 97048
Latitude 46.08895	Longitude 122.93629	
Tracking Code RVS in 2006	Inspection Date 9/20/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	2.8	-1	-0.5	-1	0	0	-0.6	0	-0.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Rainier City Police Dept City Hall

Final RVS Score

Final Type	Final Score
C2	-0.3

FEMA-154 Collapse Potential

Very High (100%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Rainier City Police Dept City Hall

Colu_pol04A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1920
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	3	No	Yes
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: T shaped		Building On Hill or Sloped Site	
None		None	
None		None	
Falling Hazards		Poor Conditions	
Other: Heavy cornice or other overhead decoration		Open cracks in structural members	
Other: General		None	
None		None	
			
E	Poor Condition	N	Poor Condition
			
N	Building Name	N	Elevation View
			
SW	Elevation View	SW	Falling Hazard
			
SW		Vertical Irregularity Primary	
			
S		Elevation View	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries