

# Columbia City School

St Helens SD 502

Colu\_sch06A

Building Type	County	
School	Columbia	
Street		
2000 Second St		
City	State	Zip
Columbia City	OR	97018
Latitude	Longitude	
45.89136	122.80879	
Tracking Code	Inspection Date	
RVS in 2006	9/1/2006	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	0	2.4	-0.4	0	0	3.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Columbia City School

### Final RVS Score

Final Type	Final Score
W2	3.3

### FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

# Columbia City School

Colu\_sch06A

Enrollment 263	Year Built (Field Verified) 1929	Year Built (Alt. Source) 1929	Est. Decade Built 1990
Total Area (square ft) 40000	Number of Stories 2	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners: Other None None		Vertical Irregularities Steps in Elevation View: 2 to 3 Changes Building On Hill or Sloped Site None	
Falling Hazards None None None		Poor Conditions None None None	
			
NW Plan Irregularity Primary	W Building Name	SW Plan Irregularity Primary	
			
SW Vertical Irregularity Secondary	SE Number of Stories	SE Vertical Irregularity Primary	
			
NE Vertical Irregularity Primary	NE Elevation View		



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries