

Warren Elementary School

Colu_sch17A

Scappoose SD 1J

Building Type		County	
School		Columbia	
Street			
34555 Berg Rd			
City	State	Zip	
Warren	OR	97053	
Latitude		Longitude	
45.81261		122.85465	
Tracking Code		Inspection Date	
RVS in 2006		8/22/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W1	4.4	-2.5	-0.5	0	0	0	0	0	1.4
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Warren Elementary School

Final RVS Score

Final Type

Final Score

W1

1.4

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
196		1903	1940
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
25000	1	No	Yes

Plan Irregularities	Vertical Irregularities
Reentrant Corners: Other	Steps in Elevation View: Single Change
Reentrant Corners: Other (Adjacent Build/Entity)	Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity)
None	Building On Hill or Sloped Site

Falling Hazards	Poor Conditions
Unreinforced Chimneys	None
Other: Brick Veneer	None
None	None



SE Vertical Irregularity Tertiary



S Falling Hazard



E Plan Irregularity Primary



NE Elevation View
conn to d




NW General Site
conn to d and c

Warren Elementary School

Colu_sch17B

Scappoose SD 1J

Building Type		County	
School		Columbia	
Street			
34555 Berg Rd			
City	State	Zip	
Warren	OR	97053	
Latitude		Longitude	
45.81245		122.85488	
Tracking Code		Inspection Date	
RVS in 2006		8/22/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	0	0	0	-0.8	0	0.5
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Warren Elementary School

Final RVS Score

Final Type

Final Score

W2

0.5

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries


Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
196		1903	1950
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
25000	1	No	Yes

Plan Irregularities	Vertical Irregularities
Reentrant Corners: Other (Adjacent Build/Entity)	Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity)
None	Building On Hill or Sloped Site
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



SW Vertical Irregularity Primary

SE Vertical Irregularity Primary
conn to a

SE Primary Structural Type

Warren Elementary School

Colu_sch17C

Scappoose SD 1J

Building Type		County	
School		Columbia	
Street			
34555 Berg Rd			
City	State	Zip	
Warren	OR	97053	
Latitude		Longitude	
45.81256		122.85514	
Tracking Code		Inspection Date	
RVS in 2006		8/22/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	0	0	0	-0.8	0	0.5
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Warren Elementary School

Final RVS Score

Final Type

Final Score

W2

0.5

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
196		1903	1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
25000	1	No	Yes

Plan Irregularities	Vertical Irregularities
Reentrant Corners: Other (Adjacent Build/Entity)	Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity)
None	None
None	None

Falling Hazards	Poor Conditions
Other: Ornamental Hazard Over Exit	None
None	None
None	None



NW Falling Hazard



NW Elevation View

W Vertical Irregularity Primary
b roof beyond

SW Elevation View

Warren Elementary School

Colu_sch17D

Scappoose SD 1J

Building Type		County	
School		Columbia	
Street			
34555 Berg Rd			
City	State	Zip	
Warren	OR	97053	
Latitude		Longitude	
45.81289		122.85455	
Tracking Code		Inspection Date	
RVS in 2006		8/22/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	0	-0.5	0	2.4	0	-0.8	0	4.9
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Warren Elementary School

Final RVS Score

Final Type

Final Score

W2

4.9

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
196		1903	1990
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
25000	1	No	Yes

Plan Irregularities	Vertical Irregularities
Reentrant Corners: Other (Adjacent Build/Entity)	None
None	None
None	None

Falling Hazards	Poor Conditions
Other: Brick Veneer	None
None	None
None	None



NE Primary Structural Type

NE Primary Structural Type
WOOD WALLNW Elevation View
no vert irr