

Coquille Fire

Coquille RFPD

Coos_fir01A

Building Type	County
Fire	Coos
Street	
89 W 3rd St	
City	State Zip
Coquille	OR 97423
Latitude	Longitude
43.17666	124.18972
Tracking Code	Inspection Date
RVS in 2006	8/10/2006



Seismicity Zone: Very High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	2.8	-1	-0.5	0	0	-0.4	0	0	0.9
Secondary	C1	2.5	-1.5	-0.5	0	0	-0.4	0	0	0.1
Tertiary		0	0	0	0	0	0	0	0	0

Coquille Fire

Final RVS Score

Final Type	Final Score
C1	0.1

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Coquille Fire

Coos_fir01A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1960
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	2	No	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners:L shaped (Adjacent Build/Entity)		Steps in Elevation View: 2 to 3 Changes	
None		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
E	Vertical Irregularity Primary	N	General Site
			
W		Primary Structural Type	
			
NE	Falling Hazard		



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries