

# Coquille Fire

Coquille RFPD

Coos\_fir21A

|               |       |                 |  |
|---------------|-------|-----------------|--|
| Building Type |       | County          |  |
| Fire          |       | Coos            |  |
| Street        |       |                 |  |
| 11261 Hwy 42  |       |                 |  |
| City          | State | Zip             |  |
| Coquille      | OR    | 97423           |  |
| Latitude      |       | Longitude       |  |
| 43.12076      |       | 124.17356       |  |
| Tracking Code |       | Inspection Date |  |
| RVS in 2006   |       | 8/10/2006       |  |



Seismicity Zone: Very High

## FEMA 154 Rapid Visual Screening Score Card

|           | Type | Basic Score | Vert Irreg | Plan Irreg | Pre-Code | Post-Bench | Soil C | Soil D | Soil E | RVS Score |
|-----------|------|-------------|------------|------------|----------|------------|--------|--------|--------|-----------|
| Primary   | S3   | 3.2         | 0          | -0.5       | 0        | 0          | -0.4   | 0      | 0      | 2.3       |
| Secondary |      | 0           | 0          | 0          | 0        | 0          | 0      | 0      | 0      | 0         |
| Tertiary  |      | 0           | 0          | 0          | 0        | 0          | 0      | 0      | 0      | 0         |

Coquille Fire

## Final RVS Score

Final Type


Final Score

S3

2.3

## FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

|                        |                             |                          |                    |
|------------------------|-----------------------------|--------------------------|--------------------|
| Enrollment             | Year Built (Field Verified) | Year Built (Alt. Source) | Est. Decade Built  |
|                        |                             |                          | 1990               |
| Total Area (square ft) | Number of Stories           | Basement                 | Pounding Potential |
|                        | 1                           | No                       | No                 |

|                              |                         |
|------------------------------|-------------------------|
| Plan Irregularities          | Vertical Irregularities |
| Torsion: Eccentric Stiffness | None                    |
| None                         | None                    |
| None                         | None                    |

|                 |                 |
|-----------------|-----------------|
| Falling Hazards | Poor Conditions |
| None            | None            |
| None            | None            |
| None            | None            |

