

Building Type		County	
EOC-Public Safety Answering P		Coos	
Street			
250 N Baxter St.			
City	State	Zip	
Coquille	OR	97423	
Latitude		Longitude	
43.17656		124.18648	
Tracking Code		Inspection Date	
RVS in 2006		8/10/2006	



Seismicity Zone: Very High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	2.8	-1	-0.5	0	0	-0.4	0	0	0.9
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Coos County Sheriff's Office

## Final RVS Score

Final Type

Final Score

C2

0.9

## FEMA-154 Collapse Potential

High (&gt;10%)



Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
	1953	1953	1950
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	3	No	No

  

Plan Irregularities	Vertical Irregularities
Reentrant Corners: Other	Steps in Elevation View: 2 to 3 Changes
Out of Plane Lateral-Force-Resistance Elements	None
None	None

  

Falling Hazards	Poor Conditions
Unreinforced Chimneys	None
None	None
None	None



NE Plan Irregularity Secondary



E Vertical Irregularity Primary



E Falling Hazard



E Plan Irregularity Primary

S Other  
There is a wooden connection from the building next to it.

W Field Verified Year Built