

North Bend Senior High School

Coos_sch09A

North Bend SD 13

Building Type		County	
School		Coos	
Street			
2323 Pacific Ave			
City	State	Zip	
North Bend	OR	97459	
Latitude		Longitude	
43.40132		124.23437	
Tracking Code		Inspection Date	
RVS in 2006		8/18/2006	



Seismicity Zone: Very High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	0	0	0	0	-0.4	0	0	2.4
Secondary	PC2	2.4	0	0	0	0	-0.4	0	0	2
Tertiary		0	0	0	0	0	0	0	0	0

North Bend Senior High School

Final RVS Score

Final Type

Final Score

PC2

2

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
706		1952	1960
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
172265	2	No	No

Plan Irregularities	Vertical Irregularities
None	None
None	None
None	None

Falling Hazards	Poor Conditions
Heavy Cladding (thick stone or concrete)	None
None	None
None	None



E Falling Hazard



North Bend Senior High School

Coos_sch09B

North Bend SD 13

Building Type		County	
School		Coos	
Street			
2323 Pacific Ave			
City	State	Zip	
North Bend	OR	97459	
Latitude		Longitude	
43.40115		124.23369	
Tracking Code		Inspection Date	
RVS in 2006		8/18/2006	



Seismicity Zone: Very High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	-0.5	0	0	-0.4	0	0	0.9
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

North Bend Senior High School

Final RVS Score

Final Type

Final Score

RM1

0.9

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
706		1952	1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
172265	1	No	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners: U shaped	Steps in Elevation View: Single Change
Out of Plane Lateral-Force-Resistance Elements	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



N Plan Irregularity Primary



S Vertical Irregularity Primary



S Plan Irregularity Secondary



North Bend Senior High School

Coos_sch09C

North Bend SD 13

Building Type		County	
School		Coos	
Street			
2323 Pacific Ave			
City		State	Zip
North Bend		OR	97459
Latitude		Longitude	
43.40171		124.23378	
Tracking Code		Inspection Date	
RVS in 2006		8/18/2006	



Seismicity Zone: Very High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	0	0	-0.4	0	0	0.9
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

North Bend Senior High School

Final RVS Score

Final Type

Final Score

W2

0.9

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
706		1952	1950
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
172265	1	No	No

Plan Irregularities	Vertical Irregularities
Torsion: Building Shape	Steps in Elevation View: 2 to 3 Changes
Non-Parallel System	Steps in Elevation View: Single Change (Adjacent Building/Entity)
Reentrant Corners: Other (Adjacent Build/Entity)	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



S Plan Irregularity Tertiary



S Plan Irregularity Tertiary



SW Plan Irregularity Primary



W Vertical Irregularity Tertiary

North Bend Senior High School

Coos_sch09D

North Bend SD 13

Building Type		County	
School		Coos	
Street			
2323 Pacific Ave			
City	State	Zip	
North Bend	OR	97459	
Latitude		Longitude	
43.40173		124.23442	
Tracking Code		Inspection Date	
RVS in 2006		8/18/2006	



Seismicity Zone: Very High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	-0.5	0	0	-0.4	0	0	0.9
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

North Bend Senior High School

Final RVS Score

Final Type

Final Score

RM1

0.9

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
706		1952	1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
172265	1	No	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners: Other (Adjacent Build/Entity)	Steps in Elevation View: Single Change (Adjacent Building/Entity)
Reentrant Corners: Other (Adjacent Build/Entity)	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



W Vertical Irregularity Primary



E Plan Irregularity Secondary



North Bend Senior High School

Coos_sch09E

North Bend SD 13

Building Type		County	
School		Coos	
Street			
2323 Pacific Ave			
City	State	Zip	
North Bend	OR	97459	
Latitude		Longitude	
43.40132		124.23278	
Tracking Code		Inspection Date	
RVS in 2006		8/18/2006	



Seismicity Zone: Very High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	-0.5	0	0	-0.4	0	0	0.9
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

North Bend Senior High School

Final RVS Score

Final Type

Final Score

RM1

0.9

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
706		1952	1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
172265	2	No	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners: Other	Building On Hill or Sloped Site
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



SE Vertical Irregularity Primary



North Bend Senior High School

Coos_sch09F

North Bend SD 13

Building Type		County	
School		Coos	
Street			
2323 Pacific Ave			
City	State	Zip	
North Bend	OR	97459	
Latitude		Longitude	
43.40069		124.23273	
Tracking Code		Inspection Date	
RVS in 2006		8/18/2006	



Seismicity Zone: Very High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	-0.5	0	0	-0.4	0	0	0.9
Secondary	C2	2.8	-1	-0.5	0	0	-0.4	0	0	0.9
Tertiary		0	0	0	0	0	0	0	0	0

North Bend Senior High School

Final RVS Score

Final Type

Final Score

RM1

0.9

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
706		1952	1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
172265	1	No	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners: Other	Steps in Elevation View: 2 to 3 Changes
Out of Plane Lateral-Force-Resistance Elements	Building On Hill or Sloped Site
None	None

Falling Hazards	Poor Conditions
Heavy Cladding (thick stone or concrete)	None
None	None
None	None



E Plan Irregularity Secondary



E Falling Hazard



NE Secondary Structural Type

NE Vertical Irregularity Secondary
sloped site

N Plan Irregularity Primary