

Coquille Valley Middle School

Coquille SD 8

Coos_sch16A

Building Type	County	
School	Coos	
Street		
1115 N Baxter St		
City	State	Zip
Coquille	OR	97423
Latitude	Longitude	
43.18427	124.18765	
Tracking Code	Inspection Date	
RVS in 2006	8/10/2006	



Seismicity Zone: Very High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	-0.5	0	0	-0.4	0	0	0.9
Secondary	C2	2.8	-1	-0.5	0	0	-0.4	0	0	0.9
Tertiary		0	0	0	0	0	0	0	0	0

Coquille Valley Middle School

Final RVS Score

Final Type	Final Score
RM1	0.9

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Coquille Valley Middle School

Coos_sch16A

Enrollment 232	Year Built (Field Verified) 1972	Year Built (Alt. Source) 1970	Est. Decade Built 1970
Total Area (square ft) 68064	Number of Stories 2	Basement	Pounding Potential No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: L Shaped		Steps in Elevation View: 2 to 3 Changes	
Reentrant Corners: Other		Building On Hill or Sloped Site	
Out of Plane Lateral-Force-Resistance Elements		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
W	Plan Irregularity Primary	NW	Vertical Irregularity Secondary
			
S	Vertical Irregularity Primary		
			
NW	Plan Irregularity Secondary		



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries