

Lincoln Elementary School

Coquille SD 8

Coos_sch22A

Building Type	County	
School	Coos	
Street		
1366 N Gould St.		
City	State	Zip
Coquille	OR	97423
Latitude	Longitude	
43.18708	124.18288	
Tracking Code	Inspection Date	
RVS in 2006	8/10/2006	



Seismicity Zone: Very High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	0	0	0	0	0	1.3
Secondary	RM1	2.8	-1	-0.5	0	0	0	0	0	1.3
Tertiary		0	0	0	0	0	0	0	0	0

Lincoln Elementary School

Final RVS Score

Final Type	Final Score
W2	1.3

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Lincoln Elementary School

Coos_sch22A

Enrollment 283	Year Built (Field Verified) 1965	Year Built (Alt. Source) 1960	Est. Decade Built 1960
Total Area (square ft) 34408	Number of Stories 2	Basement	Pounding Potential No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: Single Change	
Out of Plane Lateral-Force-Resistance Elements		Building On Hill or Sloped Site	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
E	Plan Irregularity Primary	SE	Vertical Irregularity Primary
			
		SW	Vertical Irregularity Secondary



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries