

# Crook County Middle School

Crook County SD

Croo\_sch05A

Building Type	County	
School	Crook	
Street		
100 NE Knowledge St		
City	State	Zip
Prineville	OR	97754
Latitude	Longitude	
44.30131	120.8338	
Tracking Code	Inspection Date	
RVS in 2006	7/6/2006	



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	3.6	-2	-0.5	0	0	0	-1.2	0	-0.1
Secondary	RM1	3.6	-2	-0.5	0	0	0	-1.2	0	-0.1
Tertiary	URM	3.4	-1.5	-0.5	0	0	0	-0.8	0	0.6

Crook County Middle School

## Final RVS Score

Final Type	Final Score
C2	-0.1

## FEMA-154 Collapse Potential

Very High (100%)



OregonGeology

# Crook County Middle School

Croo\_sch05A

Enrollment 726	Year Built (Field Verified) 1952	Year Built (Alt. Source) 1952	Est. Decade Built 1950
Total Area (square ft) 83238	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners: U shaped Reentrant Corners: Other None		Vertical Irregularities Steps in Elevation View: Single Change None None	
Falling Hazards Unreinforced Chimneys None None		Poor Conditions None None None	
 W Falling Hazard		 SW Seismic Upgrade	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Crook County Middle School

Crook County SD

Croo\_sch05B

Building Type	County	
School	Crook	
Street		
100 NE Knowledge St		
City	State	Zip
Prineville	OR	97754
Latitude	Longitude	
44.30137	120.83338	
Tracking Code	Inspection Date	
RVS in 2006	7/6/2006	



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	0	-0.5	0	0	0	-1.2	0	1.9
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Crook County Middle School

## Final RVS Score

Final Type	Final Score
RM1	1.9

## FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Crook County Middle School

Croo\_sch05B

Enrollment 726	Year Built (Field Verified) 1952	Year Built (Alt. Source) 1952	Est. Decade Built 1970
Total Area (square ft) 83238	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners:T shaped (Adjacent Build/Entity) None None		Vertical Irregularities None None None	
Falling Hazards None None None		Poor Conditions None None None	
 NE Elevation View			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Crook County Middle School

Crook County SD

Croo\_sch05C

Building Type	County	
School	Crook	
Street		
100 NE Knowledge St		
City	State	Zip
Prineville	OR	97754
Latitude	Longitude	
44.30086	120.83306	
Tracking Code	Inspection Date	
RVS in 2006	7/6/2006	



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	-2	-0.5	0	0	0	-1.2	0	-0.1
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Crook County Middle School

## Final RVS Score

Final Type	Final Score
RM1	-0.1

## FEMA-154 Collapse Potential

Very High (100%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Crook County Middle School

Croo\_sch05C

Enrollment 726	Year Built (Field Verified) 1952	Year Built (Alt. Source) 1952	Est. Decade Built 1970
Total Area (square ft) 83238	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners: L Shaped None None		Vertical Irregularities Steps in Elevation View: Single Change None None	
Falling Hazards None None None		Poor Conditions None None None	
 SW Plan Irregularity Primary			

# Crook County Middle School

Crook County SD

Croo\_sch05D

Building Type	County	
School	Crook	
Street		
100 NE Knowledge St		
City	State	Zip
Prineville	OR	97754
Latitude	Longitude	
44.30158	120.83234	
Tracking Code	Inspection Date	
RVS in 2006	7/6/2006	



Seismicity Zone: Moderate

**FEMA 154 Rapid Visual Screening Score Card**

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	0	-0.5	0	0	0	-1.2	0	1.9
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

**Crook County Middle School**

**Final RVS Score**

Final Type	Final Score
RM1	1.9

**FEMA-154 Collapse Potential**

Moderate (>1%)
----------------



**OregonGeology**

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Crook County Middle School

Croo\_sch05D

Enrollment 726	Year Built (Field Verified) 1952	Year Built (Alt. Source) 1952	Est. Decade Built 1970
Total Area (square ft) 83238	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners: Other None None		Vertical Irregularities None None None	
Falling Hazards None None None		Poor Conditions None None None	