

Agness Illahee FD

Curr_fir03A

Agness Illahee RFPD

Building Type		County	
Fire - RFPD		Curry	
Street			
3447 Agness Illatie Rd.			
City	State	Zip	
Agness	OR	97406	
Latitude		Longitude	
42.55722		124.06459	
Tracking Code		Inspection Date	
RVS in 2006		8/4/2006	



Seismicity Zone: Very High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W1	4.4	0	0	0	0	0	0	0	4.4
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Agness Illahee FD

Final RVS Score

Final Type

Final Score

W1

4.4

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		1990	Pre 1900
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
1539	1	No	No

Plan Irregularities	Vertical Irregularities
None	None
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None