

Winchuck RFPD

Curr_fir13A

Winchuck RFPD

Building Type		County	
Fire - RFPD		Curry	
Street			
363 Winchuck River Rd.			
City	State	Zip	
Brookings	OR	97415	
Latitude	Longitude		
42.03426	124.16581		
Tracking Code	Inspection Date		
RVS in 2006	8/4/2006		



Seismicity Zone: Very High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W1	4.4	-2.5	-0.5	0	0	0	0	0	1.4
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Winchuck RFPD

Final RVS Score

Final Type

Final Score

W1

1.4

FEMA-154 Collapse Potential

Moderate (>1%)



Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	2	No	No

Plan Irregularities	Vertical Irregularities
Torsion: Eccentric Stiffness	Steps in Elevation View: Single Change
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



SW General Site



E Plan Irregularity Primary

