

Kalmiopsis Elementary School

Brookings-Harbor SD 17C

Curr_sch03A

Building Type	County
School	Curry
Street	
650 Easy St.	
City	State Zip
Brookings	OR 97415
Latitude	Longitude
42.05937	124.28272
Tracking Code	Inspection Date
RVS in 2006	8/4/2006



Seismicity Zone: Very High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	0	0	0	0	0	1.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Kalmiopsis Elementary School

Final RVS Score

Final Type	Final Score
W2	1.3

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Kalmiopsis Elementary School

Curr_sch03A

Enrollment 686	Year Built (Field Verified) 1958	Year Built (Alt. Source) 1958	Est. Decade Built 1950
Total Area (square ft) 85768	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: E Shaped (Adjacent Build/Entity)		Steps in Elevation View: 2 to 3 Changes	
Out of Plane Lateral-Force-Resistance Elements		None	
Torsion: Eccentric Stiffness		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
W Plan Irregularity Secondary		E Vertical Irregularity Primary	
		SE General Site	
			
N Plan Irregularity Primary		N Plan Irregularity Tertiary All 3 legs of this building have a very large and deep opening.	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries