

Brookings-Harbor High School

Brookings-Harbor SD 17C

Curr_sch08A

Building Type	County	
School	Curry	
Street		
625 Pioneer Rd.		
City	State	Zip
Brookings	OR	97415
Latitude	Longitude	
42.05742	124.28018	
Tracking Code	Inspection Date	
RVS in 2006	8/4/2006	



Seismicity Zone: Very High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	0	0	0	0	0	1.3
Secondary	RM1	2.8	-1	-0.5	0	0	0	0	0	1.3
Tertiary	C2	2.8	-1	-0.5	0	0	0	0	0	1.3

Brookings-Harbor High School

Final RVS Score

Final Type	Final Score
W2	1.3

FEMA-154 Collapse Potential

Moderate (>1%)






OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Brookings-Harbor High School

Curr_sch08A

Enrollment 652	Year Built (Field Verified) 1954	Year Built (Alt. Source) 1954	Est. Decade Built 1950
Total Area (square ft) 85643	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: Very Irregular Changes	
Out of Plane Lateral-Force-Resistance Elements		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
S	Vertical Irregularity Primary	S	Plan Irregularity Primary
			
W	General Site	W	General Site
			
N	General Site	N	Secondary Structural Type
			
N	Vertical Irregularity Primary	N	Vertical Irregularity Primary
			
N	General Site	E	Tertiary Structural Type
			
N	Plan Irregularity Secondary	N	Plan Irregularity Secondary



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries