

Mazama Gym

Central Oregon CC

Desc_coc04A

Building Type Community_College	County Deschutes	
Street 2600 NW College Way		
City Bend	State OR	Zip 97701
Latitude 44.07048	Longitude 121.34885	
Tracking Code Miller 2004-05	Inspection Date 8/26/2005	

Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C1	3	-2	-0.5	0	0	0	0	0	0.5
Secondary	C2	3.6	-2	-0.5	0	0	0	0	0	1.1
Tertiary		0	0	0	0	0	0	0	0	0


Mazama Gym

Final RVS Score

Final Type	Final Score
C1	0.5

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Mazama Gym

Desc_coc04A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
	1971	1971	1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
36114	2	No	No
Plan Irregularities		Vertical Irregularities	
Yes: Unknown		Yes: Unknown	
Falling Hazards		Poor Conditions	
None			
None			
None			