

# Boyle Education Center

Desc\_coc09A

Central Oregon CC

Building Type	County	
Community_College	Deschutes	
Street		
2600 NW College Way		
City	State	Zip
Bend	OR	97701
Latitude	Longitude	
44.06772	121.34715	
Tracking Code	Inspection Date	
Missed	3/1/2007	

Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary		0	0	0	0	0	0	0	0	0
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0


Boyle Education Center

## Final RVS Score

Final Type      Final Score

## FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Boyle Education Center

Desc\_coc09A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
38454	1989	1989	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
38454	3	No	No
Plan Irregularities		Vertical Irregularities	
Falling Hazards		Poor Conditions	