

# Cascades Hall

Central Oregon CC

Desc\_coc12A

Building Type Community_College	County Deschutes	
Street 2600 NW College Way		
City Bend	State OR	Zip 97701
Latitude 44.07359	Longitude 121.34807	
Tracking Code New Building	Inspection Date 3/1/2007	

Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary		0	0	0	0	0	0	0	0	0
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0


Cascades Hall

## Final RVS Score

Final Type      Final Score

## FEMA-154 Collapse Potential

Low (<1%)



# Cascades Hall

Desc\_coc12A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
	2002	2002	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
38245	2	No	No
Plan Irregularities		Vertical Irregularities	
Falling Hazards		Poor Conditions	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries