

# Library

Central Oregon CC

Desc\_coc13A

Building Type		County	
Community_College		Deschutes	
Street			
2600 NW College Way			
City	State	Zip	
Bend	OR	97701	
Latitude		Longitude	
44.07254		121.34956	
Tracking Code		Inspection Date	
New Building		3/1/2007	

Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary		0	0	0	0	0	0	0	0	0
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Library


## Final RVS Score

Final Type

Final Score

## FEMA-154 Collapse Potential

Low (<1%)



Campus Map

(rev. 3/06)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
<input type="text"/>	<input type="text" value="1997"/>	<input type="text" value="1997"/>	<input type="text"/>
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
<input type="text" value="72250"/>	<input type="text" value="3"/>	<input type="text" value="No"/>	<input type="text" value="No"/>

Plan Irregularities	Vertical Irregularities
<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>

Falling Hazards	Poor Conditions
<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>