

Redmond - One Stop Building

Desc_coc15A

Central Oregon CC

Building Type		County	
Community_College		Deschutes	
Street			
2030 SE College Loop			
City	State	Zip	
Redmond	OR	97756	
Latitude		Longitude	
44.25578		121.16541	
Tracking Code		Inspection Date	
New Building		3/1/2007	


Seismicity Zone: Moderate										
FEMA 154 Rapid Visual Screening Score Card										
	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary		0	0	0	0	0	0	0	0	0
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Redmond - One Stop Building

Final RVS Score

Final Type Final Score

FEMA-154 Collapse Potential



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
	1998	1998	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
13788	1	No	No

Plan Irregularities	Vertical Irregularities

Falling Hazards	Poor Conditions

