

Bend FD - South Station 303

Desc_fir02A

City of Bend

Building Type		County	
Fire - City		Deschutes	
Street			
61080 Country Club Rd			
City	State	Zip	
Bend	OR	97702	
Latitude		Longitude	
44.01716		121.30331	
Tracking Code		Inspection Date	
New Building		9/15/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary		0	0	0	0	0	0	0	0	0
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Bend FD - South Station 303

Final RVS Score

Final Type

Final Score

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
<input type="text"/>	<input type="text"/>	2000	<input type="text"/>
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
<input type="text"/>	<input type="text"/>	No	No

Plan Irregularities	Vertical Irregularities
<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>

Falling Hazards	Poor Conditions
<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>