

Redmond F & R - Station 404 Cline Falls

Desc_fir08A

City of Redmond

Building Type	County	
Fire - City	Deschutes	
Street		
100 SW 67th		
City	State	Zip
Redmond	OR	97756
Latitude	Longitude	
44.27701	121.25032	
Tracking Code	Inspection Date	
New Building	6/28/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	-2	-0.5	0	0	-0.8	0	0	0.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Redmond F & R - Station 404 Cline Falls

Final RVS Score

Final Type	Final Score
RM1	0.3

FEMA-154 Collapse Potential

High (>10%)



Oregon Geology

Redmond F & R - Station 404 Cline Falls

Desc_fir08A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		1994	1990
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
7384	1	No	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: T shaped		Steps in Elevation View: 2 to 3 Changes	
None		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
NW Vertical Irregularity Primary			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries