

Redmond F & R - Station 401 Headquarters

City of Redmond

Desc_fir09A

Building Type	County	
Fire - City	Deschutes	
Street		
341 Nw Dogwood		
City	State	Zip
Redmond	OR	97756
Latitude	Longitude	
44.27969	121.17223	
Tracking Code	Inspection Date	
New Building	9/15/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary		0	0	0	0	0	0	0	0	0
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Redmond F & R - Station 401 Headquarters

Final RVS Score

Final Type Final Score

FEMA-154 Collapse Potential

Low (<1%)

Redmond F & R - Station 401 Headquarters

Desc_fir09A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		2003	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
		No	No
Plan Irregularities		Vertical Irregularities	
Falling Hazards		Poor Conditions	