

Cloverdale RFPD

Desc_fir12A

Cloverdale RFPD

Building Type Fire - RFPD	County Deschutes	
Street 68787 George Cyrus Rd.		
City Cloverdale	State OR	Zip 97759
Latitude 44.29043	Longitude 121.45336	
Tracking Code RVS in 2006	Inspection Date 6/28/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W1	5.2	-3.5	-0.5	0	0	-0.2	0	0	1
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Cloverdale RFPD

Final RVS Score

Final Type	Final Score
W1	1

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		1980	1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	2	No	No
Plan Irregularities		Vertical Irregularities	
Torsion: Building Shape		Steps in Elevation View: Single Change (Adjacent Building/Entity)	
None		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
 W Elevation View		 NW Vertical Irregularity Primary	



Cloverdale RFPD

Desc_fir12B

Cloverdale RFPD

Building Type Fire - RFPD	County Deschutes	
Street 68787 George Cyrus Rd		
City Cloverdale	State OR	Zip 97759
Latitude 44.29029	Longitude 121.45337	
Tracking Code RVS in 2006	Inspection Date 6/28/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W1	5.2	-3.5	-0.5	0	1.6	-0.2	0	0	2.6
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Cloverdale RFPD

Final RVS Score

Final Type	Final Score
W1	2.6

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		1980	1980
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: T shaped		Steps in Elevation View: Single Change	
None		Steps in Elevation View: Single Change (Adjacent Building/Entity)	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	

