

Cloverdale RFPD

Desc_fir16A

Cloverdale RFPD

Building Type		County	
Fire - RFPD		Deschutes	
Street			
67433 Cloverdale Rd			
City	State	Zip	
Cloverdale	OR	97759	
Latitude		Longitude	
44.24168		121.47343	
Tracking Code		Inspection Date	
RVS in 2006		7/5/2006	

Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W1	5.2	-3.5	0	0	0	-0.2	0	0	1.5
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Cloverdale RFPD

Final RVS Score

Final Type

Final Score

W1

1.5

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		1985	1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
2460	1	No	No

Plan Irregularities	Vertical Irregularities
None	Steps in Elevation View: Single Change
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None

