

# St. Charles Medical Center - Bend

Desc\_hos01A

Cascade Healthcare Community NFP

Building Type		County	
Hospital		Deschutes	
Street			
2500 Ne Neff Rd			
City	State	Zip	
Bend	OR	97701	
Latitude		Longitude	
44.06781		121.26907	
Tracking Code		Inspection Date	
New Building		6/30/2006	



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C1	3.2	-2	-0.5	0	0	0	0	0	0.7
Secondary	C2	4	-2	-0.5	0	0	0	0	0	1.5
Tertiary		0	0	0	0	0	0	0	0	0

St. Charles Medical Center - Bend

## Final RVS Score

Final Type

Final Score

C1

0.7

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# St. Charles Medical Center - Bend

Desc\_hos01A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		2006	1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
410000	5	No	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners: Other (Adjacent Build/Entity)	Steps in Elevation View: Very Irregular Changes (Adjacent Building/Ent
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



W Elevation View



N General Site



NE General Site



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# St. Charles Medical Center - Bend

Desc\_hos01B

Cascade Healthcare Community NFP

Building Type		County	
Hospital		Deschutes	
Street			
2500 Ne Neff Rd			
City	State	Zip	
Bend	OR	97701	
Latitude		Longitude	
44.06826		121.26878	
Tracking Code		Inspection Date	
New Building		6/30/2006	



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C1	3.2	-2	-0.5	0	0	0	0	0	0.7
Secondary	C2	4	-2	-0.5	0	1.6	0	0	0	3.1
Tertiary		0	0	0	0	0	0	0	0	0

St. Charles Medical Center - Bend

## Final RVS Score

Final Type

Final Score

C1

0.7

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries



# St. Charles Medical Center - Bend

Desc\_hos01B

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
	1993	2006	1990
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
410000	5	No	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners: Other (Adjacent Build/Entity)	Steps in Elevation View: Very Irregular Changes (Adjacent Building/Ent
None	Building On Hill or Sloped Site
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



SE Vertical Irregularity Secondary



SW General Site



W General Site



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries