

# R E Jewell Elementary School

Bend-LaPine SD 1

Desc\_sch01A

Building Type School	County Deschutes	
Street 20550 Murphy		
City Bend	State OR	Zip 97702
Latitude 44.0215	Longitude 121.29753	
Tracking Code RVS in 2006	Inspection Date 7/4/2006	



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	-2	-0.5	0	0	-0.8	0	0	0.3
Secondary	RM2	3.4	-1.5	-0.5	0	0	-0.6	0	0	0.8
Tertiary	W2	4.8	-3	-0.5	0	0	-0.8	0	0	0.5

R E Jewell Elementary School

### Final RVS Score

Final Type	Final Score
RM1	0.3

### FEMA-154 Collapse Potential

High (>10%)



OregonGeology

# R E Jewell Elementary School

Desc\_sch01A

Enrollment 678	Year Built (Field Verified) 1974	Year Built (Alt. Source) 1974	Est. Decade Built 1970
Total Area (square ft) 54252	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: Very Irregular Changes	
Out of Plane Lateral-Force-Resistance Elements		None	
None		None	
Falling Hazards		Poor Conditions	
Other: Ornamental Hazard Over Exit		None	
None		None	
None		None	
			
W Vertical Irregularity Primary	W Falling Hazard	SW Plan Irregularity Primary	
			
S Primary Structural Type	S Primary Structural Type	SE Plan Irregularity Secondary	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries