

# Bend Senior High School

Bend-LaPine SD 1

Desc\_sch04A

Building Type School	County Deschutes	
Street 230 NE 6th St		
City Bend	State OR	Zip 97701
Latitude 44.0524	Longitude 121.29542	
Tracking Code RVS in 2006	Inspection Date 7/4/2006	



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	3.6	-2	-0.5	0	0	0	0	0	1.1
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Bend Senior High School

### Final RVS Score

Final Type	Final Score
C2	1.1

### FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

# Bend Senior High School

Desc\_sch04A

Enrollment 1435	Year Built (Field Verified) 1956	Year Built (Alt. Source) 1956	Est. Decade Built 1950
Total Area (square ft) 199428	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities		Vertical Irregularities	
Out of Plane Lateral-Force-Resistance Elements		Steps in Elevation View: Single Change	
Reentrant Corners: L Shaped		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
SE Vertical Irregularity Primary		SW Plan Irregularity Primary	
			
NE Plan Irregularity Secondary		NE Plan Irregularity Secondary	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Bend Senior High School

Bend-LaPine SD 1

Desc\_sch04B

Building Type	County	
School	Deschutes	
Street		
230 NE 6th St		
City	State	Zip
Bend	OR	97701
Latitude	Longitude	
44.05208	121.29547	
Tracking Code	Inspection Date	
RVS in 2006	7/4/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

## Bend Senior High School

## Final RVS Score

Final Type      Final Score

C2 1.1

## FEMA-154 Collapse Potential

### Moderate (>1%)



# OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Bend Senior High School

Desc\_sch04B

Enrollment 1435	Year Built (Field Verified) 1956	Year Built (Alt. Source) 1956	Est. Decade Built 1950
Total Area (square ft) 199428	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: Single Change (Adjacent Building/Entity)	
Reentrant Corners: L Shaped		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
E Plan Irregularity Primary			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Bend Senior High School

Bend-LaPine SD 1

Desc\_sch04C

Building Type	County	
School	Deschutes	
Street		
230 NE 6th St		
City	State	Zip
Bend	OR	97701
Latitude	Longitude	
44.05176	121.29562	
Tracking Code	Inspection Date	
RVS in 2006	7/4/2006	



## Bend Senior High School

## Final RVS Score

Final Type      Final Score

RM1 1.1

## FEMA-154 Collapse Potential

### Moderate (>1%)



# OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Bend Senior High School

Desc\_sch04C

Enrollment 1435	Year Built (Field Verified) 1956	Year Built (Alt. Source) 1956	Est. Decade Built 1960
Total Area (square ft) 199428	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners:Other (Adjacent Build/Entity)		Vertical Irregularities Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity)	
Reentrant Corners: L Shaped		Steps in Elevation View: Single Change	
None		None	
Falling Hazards None		Poor Conditions None	
None		None	
None		None	
			
SW General Site		NE Plan Irregularity Secondary	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Bend Senior High School

Bend-LaPine SD 1

Desc\_sch04D

Building Type	County
School	Deschutes
Street	
230 NE 6th St	
City	State Zip
Bend	OR 97701
Latitude	Longitude
44.05191	121.29633
Tracking Code	Inspection Date
RVS in 2006	7/4/2006



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	-2	-0.5	0	0	0	0	0	1.1
Secondary	RM2	3.4	-1.5	-0.5	0	0	0	0	0	1.4
Tertiary		0	0	0	0	0	0	0	0	0

Bend Senior High School

## Final RVS Score

Final Type	Final Score
RM1	1.1

## FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

# Bend Senior High School

Desc\_sch04D

Enrollment 1435	Year Built (Field Verified) 1956	Year Built (Alt. Source) 1956	Est. Decade Built 1970
Total Area (square ft) 199428	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners:L shaped (Adjacent Build/Entity) None None		Vertical Irregularities Steps in Elevation View: Single Change (Adjacent Building/Entity) None None	
Falling Hazards None None None		Poor Conditions None None None	
 SE Vertical Irregularity Primary			

# Bend Senior High School

Bend-LaPine SD 1

Desc\_sch04E

Building Type	County	
School	Deschutes	
Street		
230 NE 6th St		
City	State	Zip
Bend	OR	97701
Latitude	Longitude	
44.05282	121.29558	
Tracking Code	Inspection Date	
RVS in 2006	7/4/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W1	5.2	-3.5	-0.5	0	0	0	0	0	1.2
Secondary	RM1	3.6	-2	-0.5	0	0	0	0	0	1.1
Tertiary		0	0	0	0	0	0	0	0	0

Bend Senior High School

Final RVS Score

Final Type

Final Score

RM1

1.1

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

# Bend Senior High School

Desc\_sch04E

Enrollment 1435	Year Built (Field Verified) 1956	Year Built (Alt. Source) 1956	Est. Decade Built 1970
Total Area (square ft) 199428	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners:Other (Adjacent Build/Entity) None None		Vertical Irregularities Steps in Elevation View: Single Change (Adjacent Building/Entity) None None	
Falling Hazards None None None		Poor Conditions Cracks None None	
			
W Field Verified Year Built		NW Poor Condition	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Bend Senior High School

Desc\_sch04F

Bend-LaPine SD 1

Building Type	County	
School	Deschutes	
Street		
230 NE 6th St		
City	State	Zip
Bend	OR	97701
Latitude	Longitude	
44.05288	121.29444	
Tracking Code	Inspection Date	
RVS in 2006	7/4/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

## Bend Senior High School

## Final RVS Score

Final Type	Final Score
PC1	2.7

## FEMA-154 Collapse Potential

---

Low (<1%)



# OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Bend Senior High School

Desc\_sch04F

Enrollment 1435	Year Built (Field Verified) 1956	Year Built (Alt. Source) 1956	Est. Decade Built 1960
Total Area (square ft) 199428	Number of Stories 2	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners:Other (Adjacent Build/Entity) None None		Vertical Irregularities Steps in Elevation View: Single Change (Adjacent Building/Entity) None None	
Falling Hazards Other: Ornamental Hazard Over Exit None None		Poor Conditions None None None	
			
SE General Site		S Elevation View	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Bend Senior High School

Desc\_sch04G

Bend-LaPine SD 1

Building Type	County	
School	Deschutes	
Street		
230 NE 6th St		
City	State	Zip
Bend	OR	97701
Latitude	Longitude	
44.05277	121.29622	
Tracking Code	Inspection Date	
RVS in 2006	7/4/2006	



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

## Bend Senior High School

## Final RVS Score

Final Type      Final Score

C2

## FEMA-154 Collapse Potential

### Moderate (>1%)



# Bend Senior High School

Desc\_sch04G

Enrollment 1435	Year Built (Field Verified) 1956	Year Built (Alt. Source) 1956	Est. Decade Built 1970
Total Area (square ft) 199428	Number of Stories 2	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners:Other (Adjacent Build/Entity) None None		Vertical Irregularities Steps in Elevation View: Single Change Steps in Elevation View: Single Change (Adjacent Building/Entity) None	
Falling Hazards None None None		Poor Conditions None None None	
			
W Vertical Irregularity Primary		NW Plan Irregularity Primary	
			
		NW Elevation View	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Bend Senior High School

Bend-LaPine SD 1

Desc\_sch04H

Building Type School	County Deschutes	
Street 230 NE 6th St		
City Bend	State OR	Zip 97701
Latitude 44.05296	Longitude 121.29485	
Tracking Code RVS in 2006	Inspection Date 7/4/2006	



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	3.6	-2	-0.5	0	0	0	0	0	1.1
Secondary	C1	3	-2	-0.5	0	0	0	0	0	0.5
Tertiary		0	0	0	0	0	0	0	0	0

Bend Senior High School

### Final RVS Score

Final Type	Final Score
C1	0.5

### FEMA-154 Collapse Potential

High (>10%)



OregonGeology

# Bend Senior High School

Desc\_sch04H

Enrollment 1435	Year Built (Field Verified) 1956	Year Built (Alt. Source) 1956	Est. Decade Built 1950
Total Area (square ft) 199428	Number of Stories 2	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners: L Shaped Reentrant Corners: L Shaped None		Vertical Irregularities Steps in Elevation View: 2 to 3 Changes Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity) None	
Falling Hazards None None None		Poor Conditions None None None	
			
NW Vertical Irregularity Secondary		SW Vertical Irregularity Primary	
			
		NW General Site	

# Bend Senior High School

Bend-LaPine SD 1

Desc\_sch04I

Building Type	County	
School	Deschutes	
Street		
230 NE 6th St		
City	State	Zip
Bend	OR	97701
Latitude	Longitude	
44.05269	121.29585	
Tracking Code	Inspection Date	
RVS in 2006	7/4/2006	



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	S2	3.6	-2	-0.5	0	0	0	0	0	1.1
Secondary	RM1	3.6	-2	-0.5	0	0	0	0	0	1.1
Tertiary	W1	5.2	-3.5	-0.5	0	1.6	0	0	0	2.8

Bend Senior High School

## Final RVS Score

Final Type	Final Score
S2	1.1

## FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

# Bend Senior High School

Desc\_sch041

Enrollment 1435	Year Built (Field Verified) 1956	Year Built (Alt. Source) 1956	Est. Decade Built 1980
Total Area (square ft) 199428	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: 2 to 3 Changes	
Reentrant Corners: Other		Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity)	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
N	Vertical Irregularity Primary	NE	Plan Irregularity Primary



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries