

Obsidian Middle School

Redmond SD 2J

Desc_sch12A

Building Type School	County Deschutes	
Street 1335 SW Obsidian Ave		
City Redmond	State OR	Zip 97756
Latitude 44.26323	Longitude 121.18253	
Tracking Code RVS in 2006	Inspection Date 6/29/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	S2	3.6	-2	-0.5	0	0	-0.8	0	0	0.3
Secondary	RM1	3.6	-2	-0.5	0	0	-0.8	0	0	0.3
Tertiary		0	0	0	0	0	0	0	0	0

Obsidian Middle School

Final RVS Score

Final Type	Final Score
S2	0.3

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Obsidian Middle School

Desc_sch12A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
731	1980	1980	1980
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
106239	1	No	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: Very Irregular Changes	
None		None	
None		None	
Falling Hazards		Poor Conditions	
Other: General		None	
None		None	
None		None	
			
S	Elevation View	S	General Site
			
W	Vertical Irregularity Primary	N	Elevation View
			
			
E	Field Verified Year Built	N	Secondary Structural Type



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries