

Sisters Elementary School

Sisters SD 6

Desc_sch14A

Building Type	County	
School	Deschutes	
Street		
611 E Cascade		
City	State	Zip
Sisters	OR	97759
Latitude	Longitude	
44.29081	121.54163	
Tracking Code	Inspection Date	
RVS in 2006	6/27/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	4.8	-3	-0.5	0	0	0	-1.2	0	0.1
Secondary	RM1	3.6	-2	-0.5	0	0	0	-1.2	0	-0.1
Tertiary		0	0	0	0	0	0	0	0	0

Sisters Elementary School

Final RVS Score

Final Type	Final Score
RM1	-0.1

FEMA-154 Collapse Potential

Very High (100%)



OregonGeology

Sisters Elementary School

Desc_sch14A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
475	1978	1978	1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
63000	1	No	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: T shaped		Steps in Elevation View: Single Change	
Reentrant Corners: Other		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
S Plan Irregularity Secondary		NW Plan Irregularity Primary and vert irregularity	



OregonGeology


Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Sisters Elementary School

Sisters SD 6

Desc_sch14B

Building Type School	County Deschutes	
Street 611 E Cascade		
City Sisters	State OR	Zip 97759
Latitude 44.29088	Longitude 121.54088	
Tracking Code RVS in 2006	Inspection Date 6/27/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	PC1	3.2	0	0	0	0	0	-1	0	2.2
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Sisters Elementary School

Final RVS Score

Final Type	Final Score
PC1	2.2

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Sisters Elementary School

Desc_sch14B

Enrollment 475	Year Built (Field Verified) 1978	Year Built (Alt. Source) 1970	Est. Decade Built 1970
Total Area (square ft) 63000	Number of Stories 2	Basement	Pounding Potential No
Plan Irregularities None None None		Vertical Irregularities Steps in Elevation View: Single Change (Adjacent Building/Entity) None None	
Falling Hazards None None None		Poor Conditions None None None	
 SW Primary Structural Type			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Sisters Elementary School

Sisters SD 6

Desc_sch14C

Building Type School	County Deschutes	
Street 611 E Cascade		
City Sisters	State OR	Zip 97759
Latitude 44.29083	Longitude 121.54235	
Tracking Code RVS in 2006	Inspection Date 6/27/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W1	5.2	0	0	0	1.6	0	-0.6	0	6.2
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Sisters Elementary School

Final RVS Score

Final Type

W1

Final Score

6.2

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Sisters Elementary School

Desc_sch14C

Enrollment 475	Year Built (Field Verified) 1978	Year Built (Alt. Source) 1978	Est. Decade Built 1980
Total Area (square ft) 63000	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities None None None		Vertical Irregularities None None None	
Falling Hazards None None None		Poor Conditions None None None	
 E Elevation View			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries