

# Lava Ridge Elementary School

Bend-LaPine SD 1

Desc\_sch21A

Building Type		County	
School		Deschutes	
Street			
20805 Cooley Rd			
City	State	Zip	
Bend	OR	97701	
Latitude		Longitude	
44.10664		121.28214	
Tracking Code		Inspection Date	
New Building		9/15/2006	



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary		0	0	0	0	0	0	0	0	0
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Lava Ridge Elementary School

## Final RVS Score

Final Type

Final Score



FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
635		1994	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
62000		No	No

Plan Irregularities	Vertical Irregularities

Falling Hazards	Poor Conditions