

Vern Patrick Elementary School

Redmond SD 2J

Desc_sch22A

Building Type	County		
School	Deschutes		
Street			
3001 Sw Obsidian			
City	State	Zip	
Redmond	OR	97756	
Latitude	Longitude		
44.26264	121.20313		
Tracking Code	Inspection Date		
New Building	9/15/2006		



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary		0	0	0	0	0	0	0	0	0
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Vern Patrick Elementary School

Final RVS Score

Final Type

Final Score

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
606		1995	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
55000		No	No

Plan Irregularities	Vertical Irregularities

Falling Hazards	Poor Conditions