

Summit High School

Bend-LaPine SD 1

Desc_sch23A

Building Type School	County Deschutes																																													
Street 2855 Nw Clearwater Dr																																														
City Bend	State OR		Zip 97701																																											
Latitude 44.05762	Longitude 121.36213																																													
Tracking Code New Building	Inspection Date 9/15/2006																																													
Seismicity Zone: Moderate																																														
FEMA 154 Rapid Visual Screening Score Card <table border="1"> <thead> <tr> <th></th> <th>Type</th> <th>Basic Score</th> <th>Vert Irreg</th> <th>Plan Irreg</th> <th>Pre-Code</th> <th>Post-Bench</th> <th>Soil C</th> <th>Soil D</th> <th>Soil E</th> <th>RVS Score</th> </tr> </thead> <tbody> <tr> <td>Primary</td> <td></td> <td>0</td> <td>0</td> <td>0</td> <td>0</td> <td>0</td> <td>0</td> <td>0</td> <td>0</td> <td>0</td> </tr> <tr> <td>Secondary</td> <td></td> <td>0</td> <td>0</td> <td>0</td> <td>0</td> <td>0</td> <td>0</td> <td>0</td> <td>0</td> <td>0</td> </tr> <tr> <td>Tertiary</td> <td></td> <td>0</td> <td>0</td> <td>0</td> <td>0</td> <td>0</td> <td>0</td> <td>0</td> <td>0</td> <td>0</td> </tr> </tbody> </table>				Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score	Primary		0	0	0	0	0	0	0	0	0	Secondary		0	0	0	0	0	0	0	0	0	Tertiary		0	0	0	0	0	0	0	0	0
	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score																																				
Primary		0	0	0	0	0	0	0	0	0																																				
Secondary		0	0	0	0	0	0	0	0	0																																				
Tertiary		0	0	0	0	0	0	0	0	0																																				
Summit High School Final RVS Score Final Type <input type="text"/> Final Score <input type="text"/>																																														
FEMA-154 Collapse Potential <input type="text" value="Low (<1%)"/>																																														

Summit High School

Desc_sch23A

Enrollment 1248	Year Built (Field Verified) 2001	Year Built (Alt. Source) 2001	Est. Decade Built
Total Area (square ft) 210000	Number of Stories	Basement	Pounding Potential No
Plan Irregularities		Vertical Irregularities	
Falling Hazards		Poor Conditions	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries