

# Pine Ridge Elem

Desc\_sch26A

Bend-LaPine SD 1

Building Type		County	
School		Deschutes	
Street			
19840 Hollygrape St			
City	State	Zip	
Bend	OR	97702	
Latitude		Longitude	
44.02349		121.33127	
Tracking Code		Inspection Date	
New Building		9/15/2006	



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary		0	0	0	0	0	0	0	0	0
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Pine Ridge Elem

## Final RVS Score

Final Type

Final Score



## FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
360		2004	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
46500		No	No

Plan Irregularities	Vertical Irregularities

Falling Hazards	Poor Conditions