

# LaPine Elementary School

Bend-LaPine SD 1

Desc\_sch32A

Building Type School	County Deschutes	
Street 51615 Coach Rd		
City La Pine	State OR	Zip 97739
Latitude 43.67579	Longitude 121.50657	
Tracking Code RVS in 2006	Inspection Date 6/30/2006	



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	-2	-0.5	0	0	0	-1.2	0	-0.1
Secondary	S2	3.6	-2	-0.5	0	0	0	-1.2	0	-0.1
Tertiary		0	0	0	0	0	0	0	0	0

LaPine Elementary School

### Final RVS Score

Final Type	Final Score
RM1	-0.1

### FEMA-154 Collapse Potential

Very High (100%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# LaPine Elementary School

Desc\_sch32A

Enrollment 506	Year Built (Field Verified) 1993	Year Built (Alt. Source) 1993	Est. Decade Built 1990
Total Area (square ft) 62000	Number of Stories 2	Basement No	Pounding Potential No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: H Shaped		Steps in Elevation View: 2 to 3 Changes	
None		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
	S		
E Field Verified Year Built	S Plan Irregularity Primary vert irregularity	W Number of Stories	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries