

Westside Village Magnet School at Kingston Element

Desc_sch35A

Bend-LaPine SD 1

Building Type		County	
School		Deschutes	
Street			
1101 NW 12th St			
City	State	Zip	
Bend	OR	97701	
Latitude		Longitude	
44.06014		121.32935	
Tracking Code		Inspection Date	
RVS in 2006		7/5/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	0	-0.5	0	0	0	0	0	3.1
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Westside Village Magnet School at Kingston Elementary School

Final RVS Score

Final Type

Final Score

RM1

3.1

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries


Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
179		1989	1950
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No

Plan Irregularities	Vertical Irregularities
Out of Plane Lateral-Force-Resistance Elements	None
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



SE Plan Irregularity Primary



S Primary Structural Type



S Falling Hazard



SW Plan Irregularity Secondary



S Vertical Irregularity Primary

