

Deschutes Edge Charter School

Redmond SD 2J

Desc_sch37A

Building Type	County	
School	Deschutes	
Street		
1220 NW Upas		
City	State	Zip
Redmond	OR	97756
Latitude	Longitude	
44.30452	121.17994	
Tracking Code	Inspection Date	
Missed	9/15/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary		0	0	0	0	0	0	0	0	0
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Deschutes Edge Charter School

Final RVS Score

Final Type Final Score

FEMA-154 Collapse Potential

High (>10%)

Deschutes Edge Charter School

Desc_sch37A

Enrollment 210	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
		No	No
Plan Irregularities		Vertical Irregularities	
Falling Hazards		Poor Conditions	
			
S	General Site	S	General Site
			
S	General Site	S	General Site
			
S	General Site	S	General Site
			
S	General Site	S	General Site
			
S	General Site	S	General Site



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries