

# Jacoby Auditorium

Umpqua CC

Doug\_coc05A

Building Type Community_College	County Douglas	
Street 1140 Umpqua College Rd		
City Roseburg	State OR	Zip 97470
Latitude 43.29022	Longitude 123.33421	
Tracking Code Miller 2004-05	Inspection Date 7/20/2004	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	2.8	-1	-0.5	0	0	0	0	0	1.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0


Jacoby Auditorium

## Final RVS Score

Final Type	Final Score
C2	1.3

## FEMA-154 Collapse Potential

Moderate (>1%)



# Jacoby Auditorium

Doug\_coc05A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
	1970	1970	1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
26849	1	No	No
Plan Irregularities		Vertical Irregularities	
None		Yes: Unknown	
Falling Hazards		Poor Conditions	
Heavy Cladding (thick stone or concrete)			
None			
None			



S General Site



S General Site



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries