

Sutherlin FD

City of Sutherlin

Doug_fir03A

Building Type	County
Fire - City	Douglas
Street	
250 S State St	
City	State Zip
Sutherlin	OR 97479
Latitude	Longitude
43.38865	123.31223
Tracking Code	Inspection Date
RVS in 2006	8/9/2006



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	-0.5	0	0	0	0	0	1.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Sutherlin FD

Final RVS Score

Final Type	Final Score
RM1	1.3

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	2	No	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: L Shaped		Steps in Elevation View: Single Change	
None		Internal Discontinuous Diaphragm (large internal opening)	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
W Vertical Irregularity Primary also shows a reentrant corner.		E Other W1-carport for private vehicles is attached to this building.	

